

**ANNEX B: Photos of action C4 (Restoration of natural hydrology at Lyngbos Hede, construction project)**



Laying down pipes



Laying down pipes





Establishment of weirs




Reconstructed dune heath, June 2005





Water on the heath, June 2005



Map of stretch put down in pipes ("rør", blue stripes)